

# Technical Information Bulletin

Date: 18.01.2017

## **Concerning: molded arrow on inlet&outlet elbows for 541 valve**

Dear Customer,

In our continuous efforts to further improve the quality of our products, we are implementing the following modification on the inlet/outlet elbows used on the 541 control valve.

For the indication of the flow direction, we currently apply stickers. We are replacing these stickers by indications molded in the elbows; see picture below.



*Molded arrow indication on inlet/outlet elbows*

This modification is implemented as of today, the part numbers have not been modified.

Please do not hesitate to contact us if you need any additional information on this topic.

Sofie Redig  
Technical Support