

Technical Information Bulletin

Date: 20.11.2017

Concerning: Main diaphragm retainer 541 control valve

Dear Customer,

In our continuous efforts to further improve the quality of our products, we implemented a modification on the retainer of the main diaphragm of the 541 control valve for our residential systems.

We have revised the retainer (item 37/item 39) of the main diaphragm, so the washer (item 40) on the current version can be eliminated. The new version is interchangeable with the current version.



Image 1: New version of retainer




Image 2: Current version of retainer with additional washer

This change is introduced in our production, all valves with a serial number higher than 492940 are equipped with this new retainer.

Please do not hesitate to contact us if you need any additional information on this topic.

Sofie Redig
Technical Support