

Technical Information Bulletin

Date: 20.03.2015

BULLETIN NO. 0149

Concerning: timer housing 541N control valve

Dear Customer,

In our continuous effort to further improve the quality of our products, we are implementing the following changes on all 541N control valves, which are sold separately as well as used on complete systems.



On the current valve configuration the electronic timer housing is fixed to the mounting bracket on the valve body, by means of 2 screws that go through the front of the housing and are screwed into the mounting bracket. This fixation method has now been reversed; instead of the 2 visible screws at the front of the housing, the housing is now attached by means of 2 screws at the rear side of the housing; the screws go through the mounting bracket and are screwed into the housing.

These 2 fixation screws are easily accessible, so removal of the electronic timer housing is still very straight forward. The advantage is that the front side of the electronic timer housing is now a lot 'cleaner'.

This new configuration will be introduced in our assembly after depletion of our current inventory, which is expected to happen in the next couple of days.



Please do not hesitate to contact us if you need any additional information on this topic.



Roel Gilissen
Operations Manager



a division of **Aquion, Inc**

Lammerdries-Oost 30c
B-2250 Olen - Belgium
Tel +32 (0)14 28 51 71
Fax +32 (0)14 28 51 70
infobelgium@eriewatertreatment.com
www.eriewatertreatment.com
RPR/RPM Turnhout
BTW/TVA/VAT BE 0882.738.206

